


2.00



173-A-11

gative

Vertikalusis



Horizontalis



Pavadinimas		Diametras	Atstumai		H	
Dangtis		ket.	0,15		211,22	
						Ar yra vandens?
Sienos						
Dugnas						Pastabos:
Nr.1	PE	65	v.v.	1,51	209,71	
			v.a.			
Nr.2	PE	65	v.v.	1,51	209,71	
			v.a.			
Nr.3	PE	32	v.v.	1,51	209,71	
			v.a.			
Nr.4						011 33012/18
Nr.5						Objektas:
Nr.6						SUDARE  R. LUCIUNAS
Nr.7						Patikrino R. GIRCYS
						2002m. 12men.....d