



95

173-A-15

(GATVE NR.7) RUKAINIU



Pavadinimas		Diametras	<i>Atstumai</i>		<i>H</i>	
Dangtis	<i>2ket.</i>	<i>650</i>			<i>210,30</i>	
Sienos	<i>bet.</i>					Ar yra vandens?
Dugnas	<i>bet.</i>	<i>2,0x1,6</i>	<i>2,21</i>		<i>208,09</i>	Pastabos:
Nr.1	<i>PE</i>		<i>v.v.</i>	<i>1,83</i>	<i>208,47</i>	
			<i>v.a.</i>			
Nr.2	<i>PE</i>		<i>v.v.</i>	<i>1,83</i>	<i>208,47</i>	
			<i>v.a.</i>			
Nr.3	<i>PE</i>		<i>v.v.</i>	<i>1,83</i>	<i>208,47</i>	
			<i>v.a.</i>			
Nr.4						011 33012/22 Objektas:
Nr.5						SUDARE  R.LUCIUNAS
Nr.6						Patikrino  R.GIRCYS
Nr.7						2002m.....12.....men.....d