



7a

173-A-16

Horizontalis



Pavadinimas		Diametras					
Dangtis		ket.	150			210,54	
Sienos						Ar yra vandens?	
Dugnas						Pastabos:	
	Nr.1	P/E	32	v.v.	1,77	208,77	
	Nr.2	P/E	32	v.v.	1,77	208,77	
	Nr.3						
	Nr.4						
	Nr.5						
	Nr.6						
	Nr.7						
						011 33012/22	
						Objektas:	
						SUDARE	 R. LUCIUNAS
						Patikrina	 R. GIRCYS
						2003.05	