

Varentiekis
(Komunikacija)

Sklendė
(Irenginio pavadinimas)

Kortelė Nr. 171

Vilnius
(Miestas)

Pilnatie
 (qatvé)

77/34-0270 (33-D-11)
(Plaņšeto nomenklatūra)

ŠULINIO PJUVIAI (m.)

PRI RIŠIMO SCHEMA

$$\frac{x = 6071582.26}{y = 587278.06}$$


$\rightarrow \infty$

A schematic diagram of a vertical pipe system. The pipe is shown in cross-section with a hatched top boundary. A valve, represented by two triangles pointing towards each other, is located on the vertical pipe. To the left of the valve, a horizontal line with an arrow points towards the pipe, labeled with the number '3'. To the right of the valve, a horizontal line with an arrow points away from the pipe, labeled with the number '12'.

The diagram shows a three-way valve symbol. It consists of a circle with a cross inside, representing the valve body. Three ports are shown: port 1 at the top, port 2 at the bottom, and port 3 on the left. The valve is shown in a position where port 1 is connected to port 2, and port 3 is closed.

Vertikalusis

Horizontalis



Pagavadinimas		Medžiaga	Diametras	Atstumas nuo dangčio		Altitude	Lipynės nėra
Dangtis		KET	150	—		124.84	(Medžiaga, kiekis)
Žemė		—	—	0.00		124.84	Ar yra vandens? — — nėra
Sienos		—	—	—		—	Ar yra dujų? — — nėra
Dugnas		—	—	—		—	Pastabos:
Vamzdžiai	Nr.1	PE	110	Viršus	2.00	122.84	2) - PEd110 - akle
				Apačia			
	Nr.2	PE	110	Viršus	2.00	122.84	UAB "Vilniaus topografija"
				Apačia			
	Nr.3	PE	32	Viršus	2.04	122.80	Objektas: Pilnatis g.3
				Apačia			
	Nr.4			Viršus			Sudaryt:  A.Venclovas (parašas) (pavarde)
				Apačia			
	Nr.5			Viršus			
				Apačia			
	Nr.6			Viršus			
				Apačia			
	Nr.7			Viršus			2015 m. 07 mėn. (Irenqimo tyrinėjimo data)
				Apačia			